

FOR YOUR SAFETY!

Be Alert to the Principal Sources
of Accidents!



Watch Out for Slack Action!
Don't Be A Fall Guy

Nulford to Alviso
Estudillo to Milpitas

S.F. Drawbridge to
Tracy



PROTECTION

FROM

SUN AND WIND

Non-Prescription Sun Glasses of the
Highest Optical Quality Are Available
to Train, Engine, and Yard Employees
on Deduction Order at Reduced Prices.
See Your Terminal Superintendent,
Trainmaster, or Road Foreman of Engines

Prices shown include Case and
Postage. Sales tax should be
added where applicable.



SPINS
SOUTHERN PACIFIC INDUSTRIAL
NUMBERING SYSTEM

Spins is a standard method of identifying industries and switching zones, tracks and consignee loading and unloading spots. By giving zones, tracks and spots certain designated numbers, we are able to print switch lists with the exact location to which a customer's cars is to be spotted.

A spins number contains up to six digits. The first two digits indicate the zone to which the cars is destined, the next two digits indicate the track number within the zone, the last two digits are the actual spot or coded spot.

EXAMPLE: Spins coded 473701 means that the car is for Zone 47, Track 37, Spot 01 on that track.

Zone and Track number appear on switch targets. Spot signs are placed where customers normally load or unload their cars.

Spot signs are 6" X 6" green metal signs with 4" white reflectorized numbers. These signs are placed at center of a car spot for spotting if possible from either side of car.



1. Procedures listed below must be compiled with in filling out the printed lists.
1. Cars properly spotted or placed opposite each show the letter "S" and write time placed to the nearest hour.
2. Cars not spotted according to list, opposite each show "00" for off spot code, actual location-track and or where car was placed and reason why car could not be spotted.
3. Cars pulled from the industry opposite each show the letter "P" write the time to the nearest hour, if cars left in the industrial area, show track and time.
4. Respotted or switched car, opposite each show the letter "R", new location (Zone, Track and Spot) of car and write time to closest hour.
5. Write job number, date, name and on duty time on all lists in space provided.
6. Any cars not shown on the printed lists and are pulled from an industry, write car initial and number as well as track pulled from on the Zone-Pull list.
7. Return finished printed spot and pull lists as soon as possible to instructed office.
8. If not furnished a spot and or pull list, then all cars switched must be listed on a Form 16 and turned in at instructed office.

SPOTTING CODES

- (*) Asterisk before and after a spot number indicates preferred spots.
- SPECIAL SPOT NUMBER CODED
The last two digits of a SPINS number may convey a special meaning and are listed below:
- 90 Team track spotting
- 91 Storage track
- 92 Denotes industry will either do the switching or furnish a switch list
- 93 Crane spotting
- 94 Hopper dump
- 95 Dock spotting
- 96 Piggyback
- 97 Auto Ramp
- 98 Interchange to other railroads
- 99 Open area where not possible to put up spot signs
- 00 When a car cannot be spotted according to the switch list and is left off spot, 00 will be indicated on the returned list. If car is left on a track other than designated on list, Track number & Spot where car is left will be shown in addition to 00













LANDMARK SYMBOL LEGEND
Sheet 1

Note: Not to be used in place or instead of Special Instructions or Timetable Bulletins












(cont'd)

LANDMARK SYMBOL LEGEND
Sheet 2


	Loading or Unloading Spouts		Proposed or Future Trackage
	Loading Rack		Interlocking Towers
	Ramps		Beet Dumps
	Overhead Traveling Crane		Sand or Gravel Dump
	Motorcar Takeoff		Company Phone
	Foreign Railroad or Privately Operated Trackage		Break. Trackage continues with no diverging switches.

LANDMARK SYMBOL LEGEND
Sheet 3


	Derrail		Spring Switch
	Track Crossing		Railroad Stop Signs
	Bumpers		Crossover Switches
	Operating Limit Sign		Roadway Gates
	Yard Limit Board		

W.P.R.R.


ESTUDILLO
16.5



HAYWARD
ZONE 41
SHEET 1



HAYWARD
ZONE 41
SHEET 2



ZONE 41

HAYWARD
ZONE 41
SHEET 3

- Track
- 4101
 - 4102
 - 4103
 - 4104
 - 4105
 - 4106
 - 4107

- Industry
- Pacific Entrerch
 - Pacific Entrerch
 - Estudillo Team Track
 - Estudillo #1
 - General Foods
 - General Foods
 - General Foods

Code/Spot

ZONE 41

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
4111	United Can #1	
4112	United Can #2	
4113	United Can #3	
4114	United Can #4	
4116	Hunt Wesson #6	
4117	Hunt Wesson #6-1/2	
4118	Hunt Wesson #7	
4119	Hunt Wesson #8	
4130	Hunt Wesson Can Trk.	
4140	Hunt Wesson New Warehouse	
4141	Glass Containers	
4142	Glass Containers	
4145	Hunt Wesson Picl OS	
4146	Hunt / Select UN	
4148		

ZONE 41

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
4162	Zenith / Harbor	
4166	Likit Window, Inc.	
4170	Jackson St. Team	

ZONE 43

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
4324	Kraftile	
4350	Pacific Int. Steel	
4351	Levin Metals	
4355	Levin Metals	
4356	P. G. & E.	
4358	Union City Lead	
4359	Union City Chemical	
4360	Lead	
4362	Pengo Corp.	
4363	Lead	
4364	Tuflex Glass	
4365	Vacant	
4366	Lead	
4367	Klinger Steel	
4368	Klinger Steel	



<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
4369	J. E. Higgins Lbr.	
4370	Lead	
4373	Liquid Air	
4374	Vacant	
4375	McKesson Chemical	
4376	McKesson Chemical	
4379	West Omega/Hydra	

ZONE 43

<u>Track</u>	<u>Industry</u>
4355	Levin Metals
4380	Decoto Siding
4390	BART


Code/Spot

ZONE 44
SHEET 2



ZONE 44

Track	Industry	Code/Spot
4450	Shinn Siding	
4451	Flintkote Lead	
4452	Flintkote Gyp #2	
4453	Flintkote Wallbd.	
4455	WP RR I/C #2	
4456	WP RR I/C #1	
4457	U. S. Gypsun #2	
4458	U. S. Gypsun #1	
4459	Alameda County SPU	
4462	Centerville Siding	
4463	L. S. Williams	
4471	Centerville Team	



NILES
ZONE 44
SHEET 3

APRIL 1975
REV. R.F.M.D 7-83

ZONE 44


<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
4401	Yard Track	
4402	Yard Track	
4403	Yard Track	
4411	Anchem Products #2	
4412	Spiked	
4413	Anchem Products #3	
4415	Livermore Siding	
4416	Corral Track	
4417	Caboose Track	

ZONE 44

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
4491	Mission Clay Products	
4495	Kaiser Sand	


SUNOL
35.6

TO NILES
ZONE 44
SHEET 3





EAST PLEASANTON ZONE 45

SHEET 1
APR. 1973
R.O. RIND 7-83



EAST PLEASANTON ZONE 45

SHEET 2
APRIL 1973
R.O. RIND 7-83



ZONE 45
SHEET 4
REV. 7-83

ZONE 45
SHEET 3
REV. 7-83

ZONE 45

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
4510	Sunol Siding	
4517	Scholastic Mag.	
4518	Tenneco	
4520	Pleasanton Team	

ZONE 45

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
4530	Old Pass	
4540	Middle Track	
4550	Back Track	
4560	#1 Siding	
4570	Rhodes Jamieson	
4580	Lone Star Lead	
4581	Lone Star #1	
4582	Lone Star #2	
4583	Lone Star #3	
4584	Lone Star #4	
4587	Lone Star #7	
4588	Lone Star #8	
4590	Livermore Team	
4691	Radum-Kaiser #1	

ZONE 45

Track

Industry

Code/Spot

4590	Livermore Team	
4591	Livermore Siding	
4592	Vacant	
4593	Calif. Steel	
4594	Capitol Metals	
4595	Capitol Metals	
4596	Capitol Metals	

ZONE 45


Track

Industry

Code/Spot


4593	Calif. Steel	
4594	Capitol Metals	
4595	Capitol Metals	
4596	Capitol Metals	
4597	Altamont Siding	

To DOUGHERTY
ZONE 46
SHEET 2



RADUM BRANCH
ZONE 46
SHEET 1


NOV 1973
REVISED 1-84



DOUGHERTY
SS. 8

RADUM BR.
ZONE 46
SHEET 2

APR 1983
REV. RFPD 7-83





REV. 1

ZONE 46

<u>Track</u>	<u>Industry</u>	<u>Code/spot</u>
4674	Eastman Kodak	
4675	Eastman Kodak	
4682	Dougherty Team	
4687	Vacant	
4688	04 Lumber	
4691	Radum-Kaiser #1	
4692	Radum-Kaiser #2	
4693	Radum-Kaiser #3	
4694	Radum-Kaiser #4	

TO OAKLAND
ZONE 44
SHEET 1



ZONE 47
SHEET 1
APR 1973
RTMD rev. 7-83


W.P.R.R. MAIN LINE



WARM SPRINGS

TO AUTO RAMP
ZONE 47
SHEET 5


ZONE 47
SHEET 2
APR 1973
Rev. RTMD 7-83



WARM SPRINGS
ZONE 47

SHEET 4

REV 1973
Rm REND 7-83



G.M. PLANT
ZONE 47

SHEET 3

REV 1973
Rm REND 7-83



WARM SPRINGS YARD
ZONE 47
SHEETS 28 & 4

ZONE 47

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
4715	Sunnyvale Lbr.	
4716	Dallas Smith Lbr.	
4717	Dallas Smith Lbr.	
4718	Dallas Smith Lbr.	
4719	Hubbard & Johnson	
4725	Central Cooling	
4727	Wicks	
4728	Wicks	

ZONE 47

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
4701		
through		
4714	General Motors Plant	




ZONE 48
 SHEET 1
 R.F.M.D. 7-83

ZONE 48
 SHEET 1
 R.F.M.D. 7-83

ZONE 48


<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
4830	Safeway Runaround	
4832	Vacant	
4835	Safeway	
4850	Milpitas Siding	
4855	House Track	
4856	Milpitas Team	
4858	Corral Track	



ZONE 51
SHEET 1

See Zone 51
Sheet 2

MULFORD
To Santa Clara
52002



To OAKLAND
Zone 51
Sheet 1

MULFORD
ZONE 51
SHEET 2

Rev. R.M.D. 6-03

ZONE 51

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>	<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
5100	Biggie Lead		5135	Dewey & Almy	
5101	Biggle / Pargas		5137	Kaiser Aerospace	
5102	First Western Grap		5140	Champion Pkging.	
5110	Metal Purchasing		5142	H. S. Crocker	
5111	Safeway Milk				
5118	Haskon				
5119	Haskon				
5120	New Trk. Lead				
5123	Rawson Drug				
5124	Rix Equipment				
5126	Betts Spring				
5127	Airport Lead				
5130	Thrifty Lead				
5131	Vacant				
5132	Prescolite				
5133	Haslett				
5134	Vacant				

ZONE 51


<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>	<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
5119	Haskon		5161	Airco Welding	
5127	Airport Lead		5163	Airco Welding	
5130	Thrifty Lead		5165	Vacant	
5131	Vacant		5166	Pacific Telephone	
5132	Prescolite		5168	Runaround Track	
5133	Haslett		5169	Georgia Pacific	
5134	Vacant		5170	Medallion Carpet	
5150	Clorx. Strongtie		5171	S. L. Distr. Center	
5151	Simpson		5172	Western Electric	
5152	Baloon Track		5173	Vacant	
5154	Runaround Track		5212	Chrysler Lead	
5155	Durotest				
5157	Inland Cities				
5158	Califoam				
5159	Crain Pac. Exxon				
5160	E End Baloon Trk.				

MULFORD

ZONE 52

SHEET 1



REV. 1/775
Rev. RFD 6-83




ZONE 52

Track	Industry	Code/Spot
5180-81	Crown Zellerbach	
5200	Drill	
5208	Vacant	
5210	Vacant	
5211	Vacant	
5212	Chrysler Lead	
5215	Chrysler	
5216	Chrysler	
5217	Chrysler	
5218	Kaiser Aluminum	
5219	Kaiser Aluminum	
5220	Kaiser Aluminum	
5222	Kellogg Grain	
5223	Caterpillar	

Track	Industry	Code/Spot
5224	Remo. Crown Zee	
5225	Walton Distr.	
5226	Kellogg Hopper	
5228	Chrysler	
5229	Handy Spot	
5234	Runaround	
5235	Runaround	
5236	Cyclone Fence	
5241	National Can	
5247	*Flintkote	
5248	Kellogg	
5249	Vacant	
5250	J. I. Case	
5256	Goodyear Tire	
5260	Domtar	





ZONE 53

Track
 53320
 53324
 53325
 53328
 53330
 53332
 53337
 53338
 53340
 53346
 53347
 53349
 53353

Industry
 Western Can
 Latchford Glass
 Rexall Lead
 Latchford Glass
 Vacant
 Vacant
 K&L Dostribution
 Vacant
 Raban
 International Paper
 Physics International
 International Paper
 Wheel Industries

Code/Spot

Track
 53354
 53360
 53361
 53361
 53362
 53363
 53365
 53370

Industry
 Simmons
 Sears Lead
 Cornelius
 Anheuser Busch
 Pacific Steel Supply
 States Warehouse
 Sears
 Harblson Walker

Code/Spot

ZONE 53

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
5300	Lucky Lead	
5301	Mulford Lumber	
5302	Owens Corning	
5303	Trumbull Asphalt	
5304	AM Mat Sup.	
5306	Fab Metals	
5307	Vacant	
5309	Pacific Aerosol	
5310	Chipman Warehouse	
5311	Lucky Bakery	
5312	Chipman Warehouse	
5313	Chipman Warehouse	
5320	Western Can	
5321	Vacant	

ZONE 53

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
5360	Sears Lead	
5370	Hardison Walker	
5375	Lead Track	
5376	U.S. Printing Ink	
5377	Kilsby	
5378	Walton Dist.	
5379	Unistrut	
5380	Nabisco Lead	
5382	Unistrut	
5385	Schering Corp.	

To OAKLAND
ZONE 53
SHEET 8

MP 17

MP 18

MULFORD ZONE 54 SHEET 1

REV. 1975
Rev. R.F.M.D 6-83

To Santa Clara
ZONE 54
SHEET 2

MP 19



To OAKLAND
ZONE 54, Sh. 1

MULFORD ZONE 54 SHEET 2

REV. 1973
REV. R.F.M.D 7-83

RUSSELL

MAIN LINE - 1



To Santa Clara
ZONE 55, S


Zone 54

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
5403	Dudway	
5410	Tharco	
5412	Runaround	
5413	USCO / Abbott Lb.	
5415	Oakland Toy	
5416	Cut N Ready	
5418	Ora Loma Sanitary	
5420	Galileo Capri	
5421	Warehouse West	
5423	Giant Snack	

ZONE 54


<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
5429	Delly Foods	
5430	Vacant	
5432	Vacant	
5433	Delly Foods	
5434	Vacant	
5435	Consumer Distributors	
5436	C Gruhler/Tongse	
5438	Lasalle Deitsch	
5439	Norton Lead	
5441	Lead Track	
5442	Vacant	

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
5443	Vacant	
5444	Rayovac	
5445	Vacant	
5447	Kirsch	
5448	Reynolds Alum.	
5449	Cudathy Pack	
5501	Russell Siding	




MULFORD
ZONE 55
SHEET 2

RFMD
7-03-
1-84



MULFORD
ZONE 55
SHEET 1

RFMD
2-05



ZONE 55

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
5511	Vacant	
5513	Vacant	
5530	Runaround	
5531	Alcoa Lead	
5532	Industrial Box	
5533	Libby Owens Ford	
5534	Container Service	
5535	Gateway Service	
5536	Nelsonsup, Henry D	
5537	Transbay Distributors	

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
5540	Vacant	
5541	Transbay Distributors	
5542	Transbay Distributors	
5543	March Matels	
5544	Vacant	
5545	United Dist.	
5546	United Distributors	
5547	J C Penny's	

MULLFORD
 ZONE 55
 SHEET 3
 RFND 1-05

ZONE 55

Track

Industry

Code/Spot

5551	Palestro Dis. Ctr.	
5571	Platt Music Co.	
5571	Cal Wipe	
5572	LCO	
5581	Vacant	
5582	Vacant	
5584	Allied Tubing	


ZONE 55

Track

Industry


Code/Spot

5494	Kenco	
5501	Russell Siding	
5510	Drill	
5518	Vacant	
5521	PMC	
5522	Wash Chemical	
5525	Vacant	
5529	Wash Chemical	
5530	Runaround	
5595	Thacker	
5596	Carboline	
5597	Continental Can	




MULFORD
ZONE 56
SHEET 1

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>	<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
5600	Mt. Eden Team		5622	Rhom Haas	
5602	Sonoco		5623	Rhom Haas	
5604	Herrick Iron		5624	Rhom Haas	
5610	Lead		5625	All Good Industries	
5612	Western PPR Box				
5613	Beckly Cardy				
5614	Vacant				
5615	Weyerhauser				
5616	Rohm Haas				
5617	Weyerhauser				
5618	R H Gorman				
5620	Rohm Haas				
5621	Rohm Haas				



ZONE 57

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
5701	Drill	
5702	Shasta Beverage	
5703	Vacant'	
5704	Durke Industries	
5706	Fisher Mattress	
5720	Winston Tire	
5721	Lead	
5722	Vacant	
5723	Pacific Cartage	
5724	Vacant	
5725	American McGaw	
5776	Strange	
5778	J & R Warehouse	



<u>Track</u>	<u>Industry</u>
5832	Allis Chalmers
5832	Con Agra Pet
5833	Dunlop Tire
5834	American Can (JAR)
5834	J & R Warehouse
5835	Vacant
5836	Vacant
5837	Sealed Air
5837	Southland Distr.


ZONE 58

Code/Spot

Track

Industry


Code/Spot



ALVARADO
ZONE 59

SHEET 2

APR 1973
Rev. R.F.M.D 6-83



ALVARADO
ZONE 59

SHEET 1

APR 1973
Rev. R.F.M.D 6-83

To END
ZONE 59, SM 2

To NEWARK
ZONE 64
Sheet 1

Union City Blvd.

ALVARADO CREEK

751-928Y
L-26-48-C

751-994F
L-26-84-C

ANERN

AVE

5984

5980
5984

5970
5976

5977

5965

5960
6640

5963

5964

5960

5961

5962

5963

5995

5985

5988

5990

to CNU

WUPPLE

ALVARADO ZONE 59 SHEET 3

ROAD
L-26-00V
749-913V

TO MAIN LINE
SEE: ZONE
SM. 2

STATE RT. 17

INDUSTRIAL

REMY

MAIN LEAD

STATE RT. 17

STATE RT. 17

STATE RT. 17

STATE RT. 17

STATE RT. 17

STATE RT. 17

STATE RT. 17

STATE RT. 17

STATE RT. 17


ZONE 59

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
5900	Alvarado Siding	
5909	Branson Cross	
5910	Ronald Lumber	
5911	Intercoastal Paint	
5917	Avard Garth Dist.	
5919	Rapid Steel Service	
5922	Campbell Chain	
5923	Benis Bag	
5924	Campbell Chain	
5933	Alvarado Team	

ZONE 59

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
5949	Vacant	
5960	Drill	
5963	Scott Paper	
5964	Markstein Bev.	
5965-03	R. D. Werner	
5965-04	R. D. Werner	
5965-05	American Can Hydra	
5965-06	American Can Hydra	
5965-07	American Can Hydra	
5965-08	American Can Hydra	
5976	Vacant	
5977	McKay Distbr.	
5984	Foremost McKess	
5990	Calavaras Cement	
5995	Calavaras Cement	
5997	Ameron Pipe Co.	

TO SAN FRANCISCO
ZONE 61
SHEET 2



MP 36

750.021 M
D.M. 34.4

MAIN LINE

12

TO SANTA CRUZ
NILES

TO CONVENT
ZONE 64
SHEET 1

MP 37

NEWARK ZONE 61 SHEET 1

APR. 1978
REV. RFPD 6-83



ZONE 61 SHEET 2

APR. 1978
REV. RFPD 6-83

MP 31


TO SAN FRANCISCO
ZONE 61
SHEET 2

SAN FRANCISCO BAY
DUNSMUIR

SAN FRANCISCO
BAY


MP 33

TO NEWARK
ZONE 61
SHEET 1
S.L. DUBIN




ZONE 61

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
6102	Soule Steel	
6103	Baron Blakeslee	
6104	Vacant	
6105	Jones Hamilton	
6106	Jones Hamilton	
6107	Fpster Chemical	
6108	Ashland Chemical	
6109	Ashland Chemical	
6110	Foster Chemical	
6111	Vacant	
6181	- San Francisco Bay Draw Bridge	
6180		



NEWARK BLVD DAB-381-A MP38



CEAR BLVD DAB-382-B MP39
 750-035V DAB-382-B
 750-033G


NEWARK
 ZONE 64
 SHEET 2

APR 1973
 Rev. RFPD 1-84


TO NILES
 ZONE 44
 SHEET 2

NEWARK
 ZONE 64
 SHEET 1

APR 1973
 Rev. RFPD 6-83




MP30
 749-9355
 749-9355



MP31
 750-0304
 750-0304

TO SANTA CLARA
 ZONE 64
 SHEET 3



TO OAKLAND
ZONE
SHEET 1

NILES
ZONE 64
SHEET 2

NEWARK
ZONE 64
SHEET 3

APR 1975
REV. 4-03

ZONE 64

<u>Track</u>	<u>Industry</u>
6420	American Brass
6421	Morton Salt
6423	Morton Salt
6425	Leslie Salt
6426	Leslie Salt
6428	Leslie Salt
6429	Leslie Salt
6430	Rickwell Lead
6431	Gerard Tire
6432	H. B. Fuller Co.
6440	Pabco Div. Coast
6441	Pabco Div. Coast
6442	Pabco Div. Coast
6444	Pabco Div. Coast
6445	Bay Cities Metal

Code/Spot

Track

6448	Guardian Pkg.
6449	Guardian Pkg.
6460	Gen-Mar
6462	W. R. Grace
6464	Union Chemical
6465	Vacant
6466	Sines Trucking
6468	S. Fraunz Schmidt
6470	Commercial Minerals
6475	Lead Track
6476	Thoro Systems
6480	Kaiser Alu. & Chem.
6483	Peterbilt Mtr.


Code/Spot

ZONE 64

<u>Track</u>	<u>Industry</u>
6402	A. O. Smith Co.
6404	Newark Team
6410	American Forest
6411	Vacant
6412	Inland Container
6415	Vacant
6416	Ethyl Visqueen

Code/Spot


749-9525
See ZONE 65
Sheet 2



ALBRAE
ZONE 65
SHEET 1
Rav. R.F.M.D 7-03

To SANTA CLARK
ZONE 66
Sheet 1

To OAKLAND
ZONE 64
Sheet 3



ALBRAE
ZONE 65
SHEET 2
R.M.D 7-03

See Zone 65
Sheet 1


ZONE 65

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>	<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
6520	Lead-Storage Track				
6524	Cal-Portland Cement				
6525	Union Metal Mfg.				
6527	Vacant				
6530	C T Supply				
6531	Chicago Bride Iron				
6532	Vacant				
6553	Celotex				
6559	Albrae Siding				
6560	PG&E				
6570	Vacant				

ZONE 65


<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
6535	Borden Chemical	
6540	Borden Chemical	
6541	Borden Chemical	
6542	Drill	
6543	Flemming Foods	
6545	Runaround	
6546	Louisiana Pacific	
6547	Reynolds Aluminum	
6548	Carboline	
6549	Nationwide Boiler	
6550	Ray Chemical	
6551	Abko American	
6552	Celotex Lead	
6553	Celotex	
6554	Celotex	
6555	Celotex	
6556	Drill	

TO OAKLAND
ZONE 65
SHEET 2



ZONE 66

<u>Track</u>	<u>Industry</u>	<u>Code/Spot</u>
6643	SC Water Cont.	
6644	Waste Water Cont.	



TO SANTA CLARE
ZONE 66
SHEET 2

ALVISO
ZONE 66
SHEET 1

APR 1973
RFD RAV 6-03

